Thomas 1/2 hp Rocker Piston Compressor Rebuild Kit





If your air compressor runs but does not pump air after a couple years of service, chances are the Tefflon® Piston Ring(s) needs to be replaced. Our rebuild kits will get your air compressor running like new.

Rating: Not Rated Yet
Price
$172.50

Ask a question about this product

Description

Rebuild kit for Thomas .50 rocking piston compressors contain these wearable internal components.