


## Thomas 3/4 hp Rocker Piston Compressor Rebuild Kit



If your air compressor runs but does not pump air after a couple years of service, chances are the Teflon® Piston Ring(s) needs to be replaced. Our rebuild kits will get your air compressor running like new.

Rating: Not Rated Yet

**Price**

**\$213.00**

[Ask a question about this product](#)

### Description

Rebuild kit for Thomas .75 rocking piston compressors contain these wearable internal components.